

1/2

FIG. 1

Prior Art 12




FIG. 2

Crack stop with metal removed

